Oil Field Environmental Incident Summary

Responsible Party: Williston Exploration LLC

Well Operator: WILLISTON EXPLORATION, LLC

Well Name: DAVIS CREEK 1-32H

Field Name: DAVIS CREEK Well File #: 15087

Date Incident: 9/5/2016 Time Incident: 08:30 Facility ID Number:

County: BILLINGS Twp: 139 Rng: 100 Sec: 32 Qtr: SW SW

Location Description: Due to the rain fall is was washed down the road ditches for approximately

250ft.

Submitted By: Renae Praus Received By:

Contact Person: Doug Nelson

7500 SAN FELIPE SUITE 600

HOUSTON, TX 77063

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1.3 MileDistance Nearest Water Well:1.3 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil 30 Barrels 30 Barrels

Brine Other

Description of Other Released Contaminant:

na

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

unknown

Areal Extent:

A limited amount of oil ran down the road ditch due to the rain fall during the night

Potential Environmental Impacts:

unknown

Action Taken or Planned:

James Oil Well Service, BB Hot Oil, Doug Nelson and the pumper where on location to contain the spill and cleanup the location

Wastes Disposal Location: yes

Agencies Involved:

Updates

Date: 9/6/2016 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, a small amount of oil ran off of location into the road ditch. Follow-up is necessary to ensure proper cleanup.

Date: 9/19/2016 Status: Inspection Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1430. The release of oil starts from the heater treater, runs along the access road, and continues along the road ditch about 100 ft. A couple of clay berms are in place. Hydrocarbon smell is very prevalent, along with staining. Further communication with the company is needed on cleanup.